

## Annex A

The following is an extract from the report and summarises the number of graves that failed safety tests. The full reports lists each individual plot with the name of the deceased, plot numbers, pass or failure of that memorial and costs to repair.

<b>Cotswold District Council</b>				
Date	Section	Memorial Tests	Failures	Fail Rate
<b><u>Chesterton Cemetery</u></b>				
	Section 1	347	87	25.07%
	Section 2	134	47	35.07%
	Section 3	419	75	17.90%
	Section 4	80	7	8.75%
	Section 5	142	36	25.35%
	Section 6	90	18	20.00%
	Section 7	134	11	8.21%
	Section 8	29	4	13.79%
	Section 9	53	5	9.43%
	Section 10	75	2	2.67%
	Section 11	25	2	8.00%
	Section 24	169	39	23.08%
	Section 25	209	56	26.79%
	Section 26	211	49	23.22%
	Section 27	341	17	4.99%
	Section 28	226	6	2.65%
	Section 29	58	0	0.00%
	Section 30	72	0	0.00%
	Section 31	152	15	9.87%
	Section 35	102	14	13.73%
	Section B	80	12	15.00%
	<b><u>Total Tests</u></b>	<b><u>3148</u></b>	<b><u>502</u></b>	<b><u>15.95%</u></b>
<b><u>Watermoor Burial</u></b>				
		42	1	2.38%
<b><u>Stratton Cemetery</u></b>				
-				
-	Section 3	39	1	2.56%
-	Section 5	53	8	15.09%
-	Section 6	52	7	13.46%

-	Section 7	83	3	3.61%
-	Section 8	169	4	2.37%
-	Section 9	8	0	0.00%
-	Traditional	151	18	11.92%
	<b><u>Total Tests</u></b>	<b><u>555</u></b>	<b><u>41</u></b>	<b><u>7.39%</u></b>