Item No 12:-

15/00833/LBC (CT.2547/X)

H S B C
2 Market Place
Cirencester
Gloucestershire
GL7 2NS


Item No 12:-

Replacement external ATM, removal of railings and stone steps and new internal ATM with associative works at H S B C

2 Market Place Cirencester

	Listed Building Consent 15/00833/LBC (CT.2547/X)	
Applicant:	HSBC Banking PLC	
Agent:	HLN Architects Ltd	
Case Officer:	Joanna Lishman	
Ward Member(s):	Councillor Joe Harris	
Committee Date:	10th June 2015	

Site Plan



© Crown copyright and database rights 2011 Ordnance Survey, SLA No. 0100018800

RECOMMENDATION: REFUSE

Main issues:

(a) Impact on Special Architectural and Historic Interest of a Listed Building

Reasons for Referral:

Ward Members Cllr Harris and Cllr Searles requested this be presented to Committee as they consider the proposal does not harm the fabric of the building and that the benefits out way the harm.

1. Site Description:

The application site is HSBC bank within Cirencester's Market Place. The application relates to the external ATM machine.

The site is a Grade II Listed Building located within Circncester Town Conservation Area. The site is within a Development Boundary as designated in the Cotswold District Local Plan 2001-2011.

2. Relevant Planning History:

An ATM was first permitted in this location in 1972 (CD2547/A), and it was at this time that the original window sill and the railings were breached, and a step cut into the stereobate (the continuous plinth upon which the columns sit). There have been numerous subsequent applications for minor alterations, but the overall arrangement has changed little since.

3. Planning Policies:

NPPF National Planning Policy Framework

4. Observations of Consultees:

Conservation Officer - incorporated into the Officer's Assessment.

5. View of Town/Parish Council:

Members had no objection to the internal works subject to the materials being appropriate to a Listed Building. However, object to the removal of the railings and stone steps as the proposals would diminish the attractive façade of this building.

Members objected to the external ATM works. Whilst appreciating the need to provide this facility, there are other ATMs in the area and the proposals would diminish the attractive façade of this building.

6. Other Representations:

None at the time of writing.

Applicant's Supporting Information:

Heritage Statement

8. Officer's Assessment:

Proposal

The applications seek listed building consent for a new ATM to be installed in the same location as the existing machine, with adjustments to the aperture of the machine, and works to include

C:\Users\Susanb\Desktop\Schedule.Rtf

removal of stone up-stand and plinth to allow for the ATM to meet DDA compliance. An internal ATM and associated works also require listed building consent.

(a) Impact on Special Architectural and Historic Interest of a Listed Building

The application site comprises a Grade II Listed Building. The Local Planning Authority is therefore statutorily required to have special regard to the desirability of preserving the building, its setting, and any features of special architectural or historic interest it may possess, in accordance with Section 16(2) of the Planning (Listed Building and Conservation Areas) Act 1990.

Section 12 of the National Planning Policy Framework asks that Local Planning Authorities should take account of the desirability of sustaining or enhancing the significance of heritage assets. Paragraph 132 states that when considering the impact of the proposed works on the significance of a designated heritage asset, great weight should be given to the asset's conservation. It also states that significance can be harmed through alteration or development within the setting. Paragraph 134 states that where proposals will cause harm to the significance of a designated heritage asset that is less than substantial harm, that harm should be weighed against the public benefits of those works.

Stereo bate:

The current proposal is to lower the ATM, to facilitate wheel-chair access, but includes the cutting out of the remainder of stereobate and its associated railings for the entire width of this intercolumniation (the gap between the two columns).

As well as constituting primary historic fabric, the stereobate (definition: the foundation or base upon which a building or the like is erected) comprises a fundamental part of the elevational design of the building; it is the visual plinth upon which the engaged Doric columns rest, and in classical architecture is as fundamental to the composition of the columns as the entablature that they support.

Whilst this portion of the stereobate has already been compromised by the present step, further and more extensive erosion would only exacerbate the existing level of harm.

Additionally, the removal of the remainder of the stereobate and its associated railings would further visually distinguish this bay of the building from the originally matching bays, both to the left, and on the return façade, thus further harmfully eroding the simplicity of the original composition, which had only two types of bay, the window bay, that was repeated five times, and the curved door bay on the corner.

Consequently the further removal of the stereobate and associated railings would harm the character of the listed building.

ATM:

The principle of lowering the ATM is, in itself, uncontentious; however it would entail further disruption to the historic fabric of the wall, it is not proposed to remove any of the large stone insertion that was installed the original ATM, nor to align the ATM in any way to respect the architectural design of the building, to provide some mitigating conservation benefit. Inserting the ATM very slightly (around 100 mm) lower than is currently proposed would allow both for the removal of the late-20th-century stone box, and the reinstatement of the window sill to its historic form.

Internal works:

The internal works proposed are not contentious and are considered acceptable.

9. Conclusion:

In conclusion, with the exception of the internal works and the lowering of the ATM, the proposed alterations, by reason of their design and physical impact, would further erode the classical architectural composition of the historic façade, harming the character and special interest of the listed building, and unsuccessfully preserving or enhancing the character and appearance of the surrounding conservation area, thus failing to sustain the significance of either designated heritage asset. The proposal therefore conflicts with Section 12 of the NPPF and Sections 16(2) and 66(1) of the Planning (Listed Building and Conservation Areas) Act 1990.

10. Reasons for Refusal:

The proposed alterations, by reason of their design and physical impact, would further erode the classical architectural composition of the historic façade, harming the character and special interest of the listed building, and unsuccessfully preserving or enhancing the character and appearance of the surrounding conservation area, thus failing to sustain the significance of either designated heritage asset. The proposal therefore conflicts with Section 12 of the N.P.P.F., and Polices 15 and 42 of the Cotswold Local Plan.

for ATM to meet DDA compliance.



Elevation of HSBC Bank, Cirencester.





Additional Photographs





Planning Issue



PROPOSED ELEVATIONS

		A 100 A 100 A
	Proposed Branch Elevations	
	, GL7 2NS	23/02/2015
	2 Market Place, Cirencester, Gloucestershire, GL7.2NS Elevations	As Noted
	2 Market Place, Cirencester, Glo	Ac Newson

1000	
CIRENCESTER - (GB6478)	Self Service Evergreen Programme



visites, pools and ma	barbara and in har fig.	the same of the same

SCOPE OF WORKS

**ENLARGE EXSTING APERTURES IN SECURE

**ENLARGE EXASTING APERTURE TO THE SECURED CLEARANCE FOR MACHINE BEING FITTED CHET HE IN B. AS ENISTING

**RETAIN 3N MACHINE SIGNS GRS VI PETAIN 3N MACHINE SIGNS GRS VI PETAIN 3N MACHINE SIGNS GRS VI WAKE GOOD ECCORATIONS COMPLETE MACHINE WALLS STOPPING AT A CLEARLY DEFINED FOUNT. ALL NEW MACHINES SHALL BE BOLTED DOWN WITH MA FINANS AS PRE HEBD SECURITY STANDARDS
 FIBER SECLIENT APPOINTED ALARM SPECIALIST SHALL DISCONNECT A SPECIALIST SHALL DISCONNECT A SPECIALIST SHALL DISCONNECT A SPECIALIST SHALL DISCONNECT A SHALL BE RELINE SHARLTHONS ARE ADMITTION SHALL BE REINSTATED TO USE THE SPECIALIST SHALL SHA SECOTAL - 61 mm SPACER TO BE INSTALLED
BEHNOR DEZELT DEBRIES FACE OF A IM
FORWARD BESPORE UNIT PS SCOTIA
SECURITY GROUP TO MATICH BEZEL SHAPE,
DIMENSIONS & FINANSED COLOUR
CONTRACTOR TO MAKE SUBE COMPLETED
WORK 13 WATHER TIGHT
EXISTING FLOOR TO BE CUT OUT TO ALLOW
FOR ATM TO BE LOWERED SUBJECT TO A
STREATOURAL ENDINEER COMMENTS.
FLOOR ACCESS HATCH TO BE COMPTRAED
THEE SCOPE OF WORKS - EXTERNAL ATM
EXISTING APERTURE TO HAVE REQUIRED
CLEARANCE FOR NEW MACHINE BEING FITTED
- ALTERATIONS TO THE OPENING. POWER & DATA RETAINED, WOOFIED TO SUIT NEW MACHINE TO BE INSTALLED
 EXISTING SELF SERVICE MACHINES HAVE VINY: APPLIED WRAP FEMOVE AND RESPRAY ALL BLACK . STONE STEPS & UP-STANDS TO BE REMOVED GOOD.

PLASTERTIMBER BOARDING TO INFILL
EXISTING APERTURE VOID MAKE GOOD AS SECTION OF STONE (TO MATCH EXISTING) INSTALLED ABOVE ATM ACTING AS LINTEL OVER APERTURE SENG TO ADVISE TO GIVE ACCESS TO ATM FAÇADE STONE TO BE CLEANED AND MADE DIEBOLD TRIMS TO BE INSTALLED TO MACHINES TO APPROVED SPECIFICATION 2018
REPLACEMENT SELF SERVICE MACHINES
01 INTERNAL CASH MACHINE 522
02 EXTERNAL CASH MACHINE 562 01 NCR 5877 (RL) 02 NCR 5684 RESPARY MACHINE Colour BLACK RAL 9005 N/A Stone steps & up-stands to be removed to allow for access to ATM. AREA OF REQUIRED ADJUSTMENT TO EXISTING STRUCTURE ROUTE ACTUAL ROUTE &
ROUTE ACTUAL ROUTE &
METHOLE STATEMENT SHALL SE
PROVIDED BY CENNOX , TO Section of stone (to match existing) installed above ATM - acting as initial overlaperture. S Eng to advise 2015 SELF SERVICE MACHINE EQUIPMENT 2014 SELF SERVICE MACHINE NEW EQUIPMENT SELF SERVICE MACHINE DE NO REMOVID NEW SECURE PARTITION SELF SERVICE MACHINE BEING FELOUATED --- DEMOLITION / REMOVAL EX STING STRUCTURE Existing vinyl signage to remain Existing stone (boxing surround) SERVICE AREA INFRINCEMENT FOFMD Plaster/timber boarding to infill Existing floar to be but but to allow for ATM to be lowered subject to a Structural existing aperture void. Replacement ATM installed - lowered to Floor access hatch --to be installed. Type suit DDA guidelines Engineer comments TBC by chent 021 Stone steps & up-stands to be removed to allow for access to ATM installed - lowered to surt DDA guidelines Stone to match existing Existing railings to be Existing signage to Replacement ATM removed

ANY NEW OR REPLACEMENT GLAZING TO BE 11.5MM 3 PLY IN ACCORDANCE WITH SECURITY

333

PROPOSED ELEVATION MAKE AND AND ADDRESS OF

HSBC 🖘

PROPOSED SECTION NAME AND ADMINISTRA

Self Service Evergreen Programme

PR03 Proposed Branch Elevation & Section 130314 2 Market Place, Cirercester, Gloucestershire, GL7 2NS As Noted

Planning Issue